


TEMPERATURE CRYSTAL

Accessory

Temperature measurement of the pressure sensor is required to correct for frequency changes of the pressure sensor due to temperature effects. We offer temperature crystals operating from -20 to 200C.

Custom configurations are available in addition to our standard offerings.



REFERENCE CRYSTAL

Accessory

A third crystal, the reference, is required and provides a stable frequency time base. This crystal is designed to have minimal temperature dependence over the temperature range of -20 to 200C.

We have a standard product offering and the ability to provide custom designs if required.



1601 N 5th St
Duncan, OK 73533

p: (580) 252-8893
f: (580) 252-8883

www.crystaltechinc.com